



| SPECIFICATIONS  | Cutmaster <sup>®</sup> Series | Auto-Cut <sup>®</sup> XT Series |                 | Ultra-Cut <sup>®</sup> XT Series |                  |                  |                  |
|---|-------------------------------|---------------------------------|-----------------|----------------------------------|------------------|------------------|------------------|
|   | A40, A60, A80, A120           | Auto-Cut 200 XT                 | Auto-Cut 300 XT | Ultra-Cut 100 XT                 | Ultra-Cut 200 XT | Ultra-Cut 300 XT | Ultra-Cut 400 XT |
| Cutting up to<br>1/4" (6 mm) – A40<br>3/8" (10 mm) – A60<br>1/2" (12 mm) – A80<br>5/8" (15 mm) – A120 | *                             | *                               | *               | *                                | *                | *                | *                |
| Cutting up to 5/8" (15 mm)  |                               | *                               | *               | *                                | *                | *                | *                |
| Cutting up to 1" (25 mm)  |                               | *                               | *               |                                  | *                | *                | *                |
| Cutting up to 1 1/4" (32 mm)  |                               |                                 | *               |                                  |                  | *                | *                |
| Cutting up to 1 1/2" (40 mm)  |                               |                                 | *               |                                  |                  | *                | *                |
| Cutting up to 2" (50 mm)  |                               |                                 |                 |                                  |                  |                  | *                |
| High Precision Cutting  |                               |                                 |                 | *                                | *                | *                | *                |
| Automated Gas Control   |                               |                                 |                 | *                                | *                | *                | *                |
| Non-HF Starting   | *                             |                                 |                 |                                  |                  |                  |                  |
| Air as Plasma Gas   | *                             | *                               | *               | *                                | *                | *                | *                |
| O <sub>2</sub> as Plasma Gas  |                               | *                               | *               | *                                | *                | *                | *                |
| XTremeLife™ Technology for O <sub>2</sub>   |                               |                                 |                 | *                                | *                | *                | *                |
| Ar - H <sub>2</sub> or N <sub>2</sub> as Plasma Gas   |                               | *                               | *               | *                                | *                | *                | *                |
| Water Mist Secondary  |                               | Optional                        | *               | *                                | *                | *                | *                |
| CNC Interface   | *                             | *                               | *               | *                                | *                | *                | *                |
| Remote Control  |                               |                                 |                 | *                                | *                | *                | *                |